


1. There are 3 wire need connection. Check the mark on the board and cable.
24vk(brown join blue wire) is power supply wire connect to 24v
GND (black wire)connect to GND
AND EOT (yellow wire)is the signal wire connect to IN



2. After finish connect the wire, then cover the board and EOT will looks like the follow picture

